30 Um:

Each

Monday, 05/01/2009 9:50:41 AM Julie Dawson User: **Process Sheet** : CU-DAR001 Dart Helicopters Services **Drawing Name** : BUSHING Customer Job Number : 44360 **Estimate Number** : 10308 Part Number : D26173 P.O. Number : 05/01/2009 This Issue S.O. No. : **Drawing Number** : D2617 REV D2 : NC : N/A Prsht Rev. Project Number First Issue : 05/01/2009 Type : MACHINED PARTS ; D2 **Drawing Revision** : 29991 Material **Previous Run Due Date** : 31/01/2009 Qty: Written By Checked & Approved By Comment : Est G 04.07.14 Reformat; added step 5 KJ/JLM **Additional Product** Job Number: Description: **Machine Or Operation:** Seq. #: M6061T6T0375W058 1.0 6061-T6 RD Tube .375 x.058W Comment: Qty.: 2.2964 f(s) 0.0765 f(s)/Unit Total: 6061-T6 Round Bar 1.5" Material: 6061-T6 (QQ-A-225/8 or QQ-A-200/8 or WW-T-700/6) Ø0.375" tubing x 0.058" wall (M6061T6T0.375W.058) Batch: M11027 2.0 HARDINGE Comment: HARDINGE Turn as per Folio FA437 and Dwg D2617 INSPECT PARTS AS THEY 3.0 Comment: INSPEC PARTS AS THEY COME OFF MACHINE SECOND CHECK 4.0 QC8 Comment: SECOND CHECK 5.0

20

30)

30

SMALL FAB 1

SMALL & MEDIUM FAB RESOURCE 1

Comment: SMALL & MEDIUM FAB RESOURCE 1

Deburr break all unmarked sharp edges 0.005 to 0.010

30

Dart Aer	ospace	Ltd
----------	--------	-----

Dart Ae	rospace	Lia								
W/O:				WORK ORI	DER CHANGES					
DATE	TE STEP PR			PROCEDURE CHANGE			By Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			:							
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1								
			,							
Part No	•		PAR #:	Fault Category:	NC	R: Yes	No DQ	A:	Date: _	
	R	esolution:		Disposition:	Q/	A: N/C (Closed:		Date: _	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						,
		Description of NC		Corrective Action Section B		Verification	Approval	Approval
DATE	STEP	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
							:	
	•							
				1				
						•		

NOTE: Date & initial all entries

Monday, 05/01/2009 9:50:41 AM Date: User: Julie Dawson **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: BUSHING Job Number: 44360 Part Number: D26173 Job Number: Seq. #: **Machine Or Operation:** Description: HAND FINISHING1 HAND FINISHING RESOURCE #1 6.0 Comment: Acid etch and Alodine as per QSI 005 4.1 INSPECT WORK TO CURRENT STEP 7.0 QC5 Comment: INSPECT WORK TO CURRENT STEP PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 9.0 Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Dart Aerospace L	.td
------------------	-----

W/O:				WORK ORDER CHANGES						ī
DATE	STEP		PR	OCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
;										
		·								
	ļ									
Part No	:		PAR #:	Fault Category:		NCR: Yes	No DQA	۸:	Date:	
	R	esolution:		Disposition:		QA: N/C	Closed:		Date: _	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section B		Verification	A 1	Approval	
DATE	STEP	Section A	Initial Action Description Sign & Chief Eng Chief Eng Date			Section C	Approval Chief Eng	Approval QC Inspector	
		,							
	-				1				
				·				i i	

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order: 44ろの	
Description: Bushing	Part Number: D2617-3	
Inspection Dwg: D2617 Rev: D2	Page 1 of 1	

FIRST ARTICLE INSPECTION CHECKLIST

·	Х	First Article	Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
0.857	+0.000/-0.010	850				
0.369	+0.004/-0.005	-37/				
				· · · · · · · · · · · · · · · · · · ·		
						·
				S 188		
	·					
					,	
						_
						4

Measured by:	Audited by: S	Prototype Approval:	N/A
Date: 69/01/6	Date: 09/01/14	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	04.08.09	New Issue	KJ/JLM ,	
В	06.03.08	Dwg Rev change	KJ/JLM 🔣	





DESIGN BW	ORAWN BY	DART AER	OSPACE LTD, ONTARIO, CANADA
CHECKED #	APPROVED	DRAWING NO. D2617	REV. D SHEET 1 OF 1
DATE 01.07.04		TITLE BUSHING	SCALE
.		BOSHING	1:1

2 04.09.10 HOP ADD D2617-7

A 96.10.08 NEW ISSUE


B 97.05.08 .875 WAS 1.125


C 97.06.04 0.369 DIA WAS 0.375

D 01.07.04 ADD MAT'L SPEC AND TOL./DIM. NOTE

DI 4.57.12 CORRECT TOLERANCE (NCR 779)


D2617-1 (0.375 OD x 0.058 WALL)





D2617-5 (0.500 OD x 0.058 WALL)





SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE

WORK ORDER

NOTES:

1) MATERIAL: 5052-H32 (QQ-A-225/7 OR WW-T-700/4)

OR 6061-T6 (QQ-A-225/8, QQ-A-200/8, OR WW-T-700/6)

2) BREAK ALL SHARP EDGES 0.005 TO 0.010

3) FINISH: ACID ETCH, ALODINE PER QSI 005 4.1

4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

5) ALL DIMENSIONS ARE IN INCHES

Copyright © 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.